



LEGEND	
ART1, ART2, ART3	ANTI-RECYCLE TIMER
C1, C2, C3	COMPRESSOR CONTACTOR
CCH	CRANKCASE HEATER
1CR, 2CR, 3CR, 4CR	CONTROL RELAY
CYC1, CYC2, CYC3	CYCLE COUNTER
DSW1	DISCONNECT SWITCH
FU1, FU2	TR1 PRIMARY CIRCUIT FUSES
FU3	TR1 SECONDARY CIRCUIT FUSE
LOR	LOCKOUT RELAY
OLR1, OLR2, OLR3	COMPRESSOR OVERLOAD RELAY
PDB1	POWER DISTRIBUTION BLOCK
PWM1	POWER MONITOR
PSH1	HIGH PRESSURE SWITCH
PSL1	LOW PRESSURE SWITCH, (P100AA-2 OPENS 35 PSI)
PSL2	LOW PRESSURE SWITCH, (P100AA-1 OPENS 25 PSI)
RHM1, RHM2, RHM3	RUN HOUR METER
TDR1	LOW SUCTION FAULT DELAY RELAY
TDR2	COMPRESSOR START DELAY RELAY
TR1	208,240,480/120 VAC 250 VA TRANSFORMER
TSH1, TSH2, TSH3	COMPRESSOR HIGH TEMPERATURE SWITCH

- NOTES:**
- ALL DASHED ----- WIRE IS FIELD INSTALLED.
 - OVERLOAD SETTINGS:
10 TON COMPRESSORS; 230V = 52A, 460V = 23A
15 TON COMPRESSORS; 230V = 77A, 460V = 34A
3. SET TDR1 TO 120 SEC. SET TDR2 TO 5-10 SEC
4. SET ART1 AND ART3 TO 4 MIN. SET ART2 TO 5 MIN.
5. CLIP THE LOOPED WIRE ON ART1, ART2, ART3 AND TDR2 AS INDICATED FOR 120/240V OPERATION.

IMPORTANT

The information contained hereon, which is the property of NAPPS INDUSTRIES, INC., must be maintained in strict confidence and no portion of this material may be reproduced or used for any purpose without the express written consent of NAPPS INDUSTRIES, INC.

ENGINEER'S SEAL	BY	DATE	REVISION	NAPPS INDUSTRIES, INC.	
				P.O. BOX 2546 - LONGVIEW, TEXAS 75606-2546	
				TRANE SCROLL COMPRESSOR UNIT	
SCALE: N/A	DRAWN BY:	CHECKED BY:	APPROVED BY:		
DATE: 11/23/04				POWER AND CONTROL WIRING SCHEMATIC 35, 40 AND 45 TON SCROLL COMPRESSOR 300	
DRAWING NUMBER: NII-400-2688	SHEET NUMBER: 1 OF 1			DRAWING B JOB NO: 000000	